

INCIDENT REPORT

Kode : GGM25-001102

Description	Oriana C2 P1 Villa Mas DOWN		
Actual Downtime	Start 2025-12-19T13:47	End 2025-12-19T18:37	Duration 4.83333333333333 hours
Root Cause	Kabel FO putus ketarik alat berat		
Solution	Splice Ulang kabel FO 2 sambungan		
Improvement	Short term - Long term -		

A. Start of the Incident

Datetime	Description
----------	-------------

B. Problem Identification

Datetime	Description
----------	-------------

C. Incident Cause

Datetime	Description
----------	-------------

D. Corrective Actions

Datetime	Description
----------	-------------

E. Service Recovery

Datetime	Description
----------	-------------

F. Attachments

#	Description	Photos / Screenshot
---	-------------	---------------------