

INCIDENT REPORT

Kode : GGM26-000239

Description	OLT Puri 2 C1 P8 Buana Duta Bandara DOWN		
Actual Downtime	Start 2026-05-06T11:09	End 2026-05-06T17:03	Duration 5.9 hours
Root Cause	FO Cut 1.3km dari odc griya kda kearah buana duta bandara		
Solution	sambung ulang kabel dan perapian kabel		
Improvement	Short term - Long term -		

A. Start of the Incident

Datetime	Description
----------	-------------

B. Problem Identification

Datetime	Description
----------	-------------

C. Incident Cause

Datetime	Description
----------	-------------

D. Corrective Actions

Datetime	Description
----------	-------------

E. Service Recovery

Datetime	Description
----------	-------------

F. Attachments

#	Description	Photos / Screenshot
---	-------------	---------------------